

Approved For Release 1999/09/07: CIA-RDP71B00263R000200170122-5

25X1A2g

IN-88060

5921)

PAGE TWO

THOUGHT IS THAT THE WOULD BE A WAY TO GET THE 25X1C8c BACK IN GEAR, RACK UP A COUPLE OPS MISSIONS FOR THE RECORD AND COVER SOME MUCH NEEDED REAL ESTATE. WITH THE CAPABILITY OF GENERATING ONLY ONE AIRCRAFT I WOULD BE RELUCTANT TO FORWARD THE ABOVE SUGGESTION.

CAMERA MISSIONS VS THE "URGENT" REQUIREMENT TO RETURN A

25X1A2g
MK IIIA TO
MY RECOMMENDATION IS TO GET REFURBISHED
MK IIIA FROM PLANT AT EARLIEST POSSIBLE TIME - EVEN IF THAT
TIME IS SIXTY DAYS OR SO HENCE - ALLOW US TO RETAIN TWO
MK IIIA'S AND CONSIDER ALERTING US FOR "H" MSN AS SOON AS
WE GET THE CAMERA OPERATIONAL.

25X1D0a

25X1D0a

4. FYI. MY GRAPE VINE TELLS ME

EXACT EXTENT OF

COVERABLE NOT DISCERNABLE AT THIS TIME.

CEC PE TOR: 17/0809Z JUL 67